

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1		
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32		
PILOT		OTHERS		AIRFRAME FAILURE										ENGINE FAILURE																			
CAUSES OF ACCIDENTS																																	
UNIT		COM.		PLACE										DATE		TIME																	
10 S.F.T.S.				Aerodrome										23-11-41		0005																	
Dauphin, Manitoba		#2												H.O. FILE		1100-79-38																	
A/C TYPE		No.		CRASH CAT.		SE		ME		DAY		NIGHT																					
Cessna Crane		7938		"C"		X		X				X																					
NAME			RANK		No.		DUTY		INJURIES				SERIOUS																				
Bain, D.T.			LAC		R97985		P		Uninjured				FATAL INJURY																				
												CARD SERIAL NO.																					
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS																					
Crane		7938		SLIGHT								INST. NIGHT		ON TYPE		TOTAL		LAST 6 MOS.															
												DUAL SOLO		DUAL SOLO																			
												19 4		37 29		67 60																	
JACOBS		4421		NIL																													
JACOBS		4420		NIL																													
SIGNAL No. & DATE			UNIT No. & DATE			COM. No. & DATE			REPORT			FILE			DATE																		
A122			23-11-41																														
NATURE OF ACCIDENT																																	
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32		
CATEGORY		TYPE OF ENGINE										TYPE OF A/C										STAGE OF FLIGHT		CAUSES									
D C B A		1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32										1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32										1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19		1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19									
D C B A		1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32										1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19 20 21 22 23 24 25 26 27 28 29 30 31 32										1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19		1 2 3 4 5 6 7 8 9 10 11 12 13 14 15 16 17 18 19									

HAND Q
 INSTS.
 WEATHER
 DRKNS.
 ALG SURF.
 OTHER
 UN'D TD
 PRIMARY
 TAKING
 LANDING
 TAKE-OFF
 FLIGHT
 STAFFRY
 FATAL
 INJ.
 3RD.

DUTY ON WHICH ENGAGED:

Night solo.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

RL70

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

Taxied into heavy snow. Aircraft
propellor swing into runway markers
damaging starboard propellor.

T. D. ...

RECOMMENDATIONS:

NIL

PRIMARY CAUSE:

HEAVY SNOW FALL ON RUNWAYS.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

HAD ALL SIMILAR TYPES OF MARKERS REMOVED.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

AIRCRAFT TAXIED INTO A RUNWAY TREE MAKER.

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____