

DUTY ON WHICH ENGAGED: Formation

Flight
Returning from detachment at
Hagersville to Camp Borden.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Aircraft returning from detachment
at Hagersville to Camp Borden.
No trace of the aircraft or pilot
to date January 6.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

Court Of Inquiry

DATE: 16-12-42

INK

COMPOSITION:

President	S/L	E.K.G. Burden	(G2046)
Members	Flt.Lt.	E.F. Lundberg	(G2844)
"	F/O	A.A. Buchanan	(G2624)

RECOMMENDATIONS:

PRIMARY CAUSE:

Unknown

No recommendation is possible.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil

Conclusions of AIB

Weather conditions encountered proved too great
a handicap for this pilot, probably aggravated by a
physical weakness. Notwithstanding the fact that four
fellow instructors, who gave evidence, divided
equally in assessing the ability of the pilot on
instruments as "average".

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

CHECKED BY

DATE