

CASPIR Aircraft Accident Cards

Serial: AJ927

Title: North American Harvard Mk. II serial:AJ927 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1941-December-20. Harvard II s/n AJ927. This accident involved 2 people. Cumming JH, Hoare CJ

Keywords: RAFHarvard II,AJ927,39 SFTS,39 Service Flying Training School,Aerodrome,1941-December-20,Cumming,HoareRCAF L20

Created: 1941-12-20

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ927>

DUTY ON WHICH ENGAGED:

Dual instruction.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

R170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Swing on landing damaging wing tip
ailerons

DATE:

4/5/85

COMPOSITION:

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

Instructor failed to correct swing.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

**Accident discussed with Instructor. No disciplinary
action taken.**

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Pupil swung on landing.

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____