

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1																																																																																				
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32																																																																																				
TECH.																	DISOB.											NEG/ICE				INEXP/NC			MISCEL.			INSTRUCT.			FLT. CONTR.			OTHERS			PRIMARY			FL. CONTR.			MOV. SURFS.			STAB. SURFS.			W. STRUTS			LAND GEAR			FLOATS			FUSE. OR HULL			TAIL SKID OR W.			ENGINE MOUNT.			MISCEL.			UND/TD			PRIMARY			FUEL SYS.			COOL SYS.			IGNIT. SYS.			LUBIN SYS.			ENG. STR.			AIRSCREW A.			ENG. CONTR.			MISCEL.			UND/TD			PRIMARY		
PILOT										OTHERS										AIRFRAME FAILURE										ENGINE FAILURE																																																																																					
CAUSES OF ACCIDENTS																																																																																																																			
UNIT 13 S. F. T. S.										COM.					PLACE 1 1/2 miles West of										DATE 21-12-41					TIME 1300																																																																																					
St. Hubert, P.Q.										3					St. Saviour des Monts										H.O. FILE 1700-31-45																																																																																										
A/C TYPE Harvard										No. 3145					CRASH CAT. A					SE X		ME		DAY X			NIGHT																																																																																								
NAME										RANK			No.			DUTY			INJURIES										SERIOUS																																																																																						
Coulter, A.H.										P/O			J. 6285			P.			Killed										FATAL	INJURY																																																																																					
Jennings, R.P.										L.AC			R96324			P.P.			Dangerously injured										1	1																																																																																					
																										CARD SERIAL No.																																																																																									
TYPE A/F & ENGINE										No.			EXTENT OF DAMAGE			REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS																																																																																													
Harvard										3145			Serious									INST.		NIGHT		ON TYPE		TOTAL		LAST 6 MOS.																																																																																					
																								DUAL		SOLO		DUAL		SOLO																																																																																					
Wasp S3B1										4701			Total									33		21		44		163		126		265																																																																																			
																						13		Nil		14		16		48		45																																																																																			
SIGNAL No. & DATE										UNIT No. & DATE					COM. No. & DATE					REPORT					FILE					DATE																																																																																					
A 90										21-12-41																																																																																																									
NATURE OF ACCIDENT																																																																																																																			

18
19
17
16
15
14
13
12
11
10
9
8
7
6
5
4
3
2
1
 HANDO. PRIMARY
 INSTS. WEATHER
 DRKNS. ALG SURF.
 OTHER UND/TD
 PRIMARY
 TAXIING LANDING
 TAKE-OFF FLIGHT
 STAFFRY FATAL
 INJ. 3RD. 2ND. 1ST.

DUTY ON WHICH ENGAGED:

Day practice flight sequence 19
(Instrument Flying Practice)

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Aircraft struck hilltop

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

Court of Inquiry

DATE:

22-12-41 IACG/POL ✓

COMPOSITION:

President: S/L S.Volk (C951)

Member: F/O A.R.C. Glibbon (C3574)

" F/O K.L. Morham (C1484)

RECOMMENDATIONS:

Disciplinary action against low flying offenders.

PRIMARY CAUSE:

Needless, unauthorized low flying.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Error in judgment on part of pilot,
resulting in a collision with a hill.

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____