

TYPE OF A/C		TYPE OF ENGINE		CATEGORY		TYPE OF A/C		TYPE OF ENGINE		CATEGORY	
UNIT	#37 S.F.T.S.	COM.		PLACE		DATE	19-12-41	TIME	1915		
Calgary, Alberta		#4		Main airdrome, Calgary		H.Q. FILE					
A/C TYPE	Oxford	No.	AS442	CRASH CAT.	"C"	SE	ME	DAY	NIGHT		
NAME		RANK	No.	DUTY	INJURIES		SERIOUS				
Rahone, J.H.M.		F/Lt.	90226	FI	Uninjured		FATAL		INJURY		
Hickling, M.B.		Sgt.		2P	Uninjured						
							CARD SERIAL NO.				
TYPE A/F & ENGINE		No.	EXTENT OF DAMAGE	REPORT FORM	SERIAL No.	DATE	HOURS FLOWN BY PILOTS				
Oxford AS802			Serious				INST.	NIGHT	ON TYPE	TOTAL	LAST 6 MOS.
Cheetah A159594			Nil				15	65	DUAL	SOLO	
Cheetah A159472			Slight						DUAL	SOLO	
SIGNAL No. & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT		FILE		DATE	
NATURE OF ACCIDENT											

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

Night flying practice.

R170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

During night flying aircrew
struck a fir tree and snow marker
on edge of taxi strip.

700/107

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

Error of judgement by pilot in going
over edge of taxi strip.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Fir tree markers shortened so that aircrews clear
them.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Marker lamp by fir tree had been
accidentally extinguished by slipstream.
Aircrew struck on edge of taxi strip.

RECORDED BY

DATE

CHECKED BY

DATE