

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	19																																																																					
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33																																																																					
JU.		TECH.		DISOB.		NEG'NCE		INEXP'NCE		MISCEL.		INSTRUCT.		FLT CONTR.		OTHERS		PRIMARY		FL. CONTS.		MOV. SURFS.		STAB. SURFS.		W. STRUTS		LAND. GEAR		FLOATS		FUSE. OR HULL		TAIL SKID OR W.		ENGINE MOUNT.		MISCEL.		UND'TD		PRIMARY		FUEL SYS.		COOL SYS.		IGNIT. SYS.		LUB'N SYS.		ENG. STR.		AIRSCREW A.		ENG. CONTS.		MISCEL.		UND'TD		PRIMARY		HAND O.		INSTS.		WEATHER		DRKNS.		ALG SURF.		OTHER		UND'TD		PRIMARY		TAXIING		LANDING		TAKE-OFF		FLIGHT		STAIRY		FATAL		INI.		INJURY		3RD.		2ND		1ST	
PILOT										OTHERS										AIRFRAME FAILURE										ENGINE FAILURE																																																																							
CAUSES OF ACCIDENTS																																																																																																					
UNIT										COM.					PLACE					DATE					TIME																																																																												
C.F.S.										# 1					Main Aerodrome Trenton					29-12-41					1830																																																																												
Trenton, Ontario																				H.Q. FILE																																																																																	
A/C TYPE										No.					CRASH CAT.					SE					ME					DAY					NIGHT																																																																		
Cessna Crane										8006					"C2"										x					x																																																																							
NAME										RANK					No.					DUTY					INJURIES					SERIOUS																																																																							
Wilkinson, R.N.															J6383					FI					Uninjured					FATAL					INJURY																																																																		
Fry, W.A.															J8368					PP					Uninjured																																																																												
																														CARD SERIAL NO.																																																																							
TYPE A/F & ENGINE										No.					EXTENT OF DAMAGE					REPORT FORM					SERIAL No.					DATE					HOURS FLOWN BY PILOTS																																																																		
C. Crane										8006					Serious																				INST.		NIGHT		ON TYPE		TOTAL		LAST 6 MOS.																																																										
Jacobs										21691					Nil															45		34		3		100		125		400																																																													
LAMB										21690					Nil															24		2		15		5		96		90																																																													
SIGNAL No. & DATE										UNIT No. & DATE					COM. No. & DATE					REPORT					FILE					DATE																																																																							
A717										29-12																																																																																											
NATURE OF ACCIDENT																																																																																																					

TYPE OF A/C

TYPE OF ENGINE

CATEGORY

MISCELLANEOUS

FLIGHT O

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

R170

Flying

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

TM/USG/XG M

While returning on taxi path for another take-off, the said aircraft passed over a patch of ice covering a hole. The ice gave way allowing the starboard wheel to drop, causing damage to the starboard undercart and aircrew³.

RECOMMENDATIONS:

PRIMARY CAUSE:

Nil

Aircraft taxied over ice which broke allowing starboard wheel to drop into a hole.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Starboard oleo leg gave way causing damage to the aircrew.

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____