

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1		
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32		
PILOT		OTHERS		AIRFRAME FAILURE										ENGINE FAILURE																			
CAUSES OF ACCIDENTS																																	
UNIT		COM.		PLACE										DATE		TIME																	
#32 E.F.T.S.														5-12-41		1130																	
BOWDEN, ALBERTA.		# 4		AERODROME.										H.Q. FILE		1100-50/22																	
A/C TYPE		No.		CRASH CAT.		SE		ME		DAY		NIGHT																					
TIGER MOTH TIGER MOTH		5016 D 5022		NIL "C1"		X				X																							
NAME				RANK		No.		DUTY		INJURIES				SERIOUS																			
BUTLER, R.T. 5016 D				LAC		1384335		P		UNINJURED				FATAL INJURY																			
BISHOP, D.J. 5022				LAC		1384835		P		UNINJURED																							
														CARD SERIAL NO.																			
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS																					
T. MOTH		5016		Nil								INST. NIGHT		ON TYPE		TOTAL		LAST 6 MOS															
T. MOTH		5022		Slight				Bishop		2 Nil		16 7		16 7																			
G. Major		7544		Nil																													
SIGNAL No & DATE				UNIT No & DATE				COM. No & DATE				REPORT		FILE		DATE																	
A124 5/12/41																																	
NATURE OF ACCIDENT																																	

TYPE OF A/C

TYPE OF ENGINE

CATEGORY

MISCELLANEOUS CAUSES

STAGE OF FLIGHT

UN'D/TD
PRIMARY
HAND Q
INSTS.
WEATHER
DRINKS.
ALG SURF.
OTHER
UN'D/TD
PRIMARY
TAXIING
LANDING
TAKE-OFF
FLIGHT
STATRY
FATAL
INJ. 3rd.

