



DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

2634 testing a/c for night flying.

Aircraft 2519 flying training.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE: R170

COMPOSITION:

Aircraft 2634 taxied into aircraft 2519.

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Carelessness on part of pilot of 2634 in that he hit 2519~~

Nil

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Pilot of 2634 severely reprimanded & fined \$35.00

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~A/C 2634 taxied into 2519~~

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_

*9111*  
*TCA/PCT*  
*TCA/XD*