

	· · · · · · · · · · · · · · · · · · ·	· · · · · · · · · · · · · · / / ›	
1	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	
	Night navigation exercises.	OR COMMANDING OFFICER'S REPORT: INVESTIGATING OFFICER'S REPORT	
	NATURE OF ACCIDENT AND STAGE OF FLIGHT: Weather conditions at home airport necessitated landing at tembina. Came in high over unlighted small rough field, overshot, ran through fence, hit ditch and came to rest in ploughed field. PRIMARY CAUSE:	Conditions at home airport ated landing at tembina. Thigh over unlighted small eld, overshot, ran through it ditch and came to rest hed field. DATE: 26-1-42 COMPOSITION: F.O. Buller, A.E. No. 7 Air Observer School, Portage la Prairie, Man. RECOMMENDATIONS: Units carrying out night flying should report immedicate over teletype sudden adverse weather conditions. Had report been sent out by No. 12 S.F.T.S. at 1800	
)	O vershot on landing .	hours when that Unit cancelled night flying, No. 1 A.O.S. would have followed suit.	
4	SECONDARY CAUSE OR CONTRIBUTING FACTORS: Forced landing on unlighted rough	TION TAKEN: (A) DISCIPLINAR Ni(B) TECHNICAL (C) OTHER conclusions of A.I.B. The cause of the accident was overshooting on landing ter being forced down by bad weather. There were ctenuating circumstances however, as the landing was ade at night on an unfamiliar airport with no flare th, the field being small, the surface rough and icy.	
	landing surface, ran through fence and hit ditch.	RECORDED BY DATE	
)	CHECKED BY DATE	