

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	
Solo practice.	OR COMMANDING OFFICER'S REPORT:	
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: R170	
Aircraft landing in flight acro		
wind swung right resulting in g	round	
loop.		
	RECOMMENDATIONS:	
	Nil	
PRIMARY CAUSE:		
Inadequate corrective action -		
swerve in landing,		
(2)	ACTION TAKEN:	
	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER	
2 8 117 1 2 0	Further instruction in landing,	
	in tanality	
U		
SECONDARY CAUSE OR CONTRIBUTING FACTORS:		
Aircraft ground looped underca		
bucking.	RECORDED BY	DATE