

## CASPIR Aircraft Accident Cards

---

**Serial:** AS854

**Title:** Airspeed Oxford Mk. II serial:AS854 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1942-January-15. Oxford s/n AS854. This accident involved 1 person. Hyde RM

**Keywords:** RAFOxford ,AS854,35 SFTS,35 Service Flying Training School,Aerodrome,1942-January-15,HydeRCAF L20

**Created:** 1942-01-15

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#AS854>



DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

Flying

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

R170

COMPOSITION:

03/2/1968

When taking off aircraft swung off the runway and hit low trees outside the aerodrome boundary.

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

~~Faulty cockpit drill.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Pupil given further instructions in cockpit drill and Log Book endorsed.

12

12. Swung

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Pilot attempted to take off with flaps down.~~

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_