

DUTY ON WHICH ENGAGED:

First solo on type

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT: **R170**

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Hit edge of cement apron at beginning of runway and wheels folded back.

DATE:

COMPOSITION:

6/2/50

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

~~Pilot's attention distracted by safety covering of firing button falling onto cockpit floor.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Pilot warned. Firing button safety cover changed.

7. Other

7

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Aircraft hit edge of cement apron at beginning of runway.~~

34 W/G Strain

34

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____