

DUTY ON WHICH ENGAGED: Sequence 3-6-7-8 Night Flying. NATURE OF ACCIDENT AND STAGE OF FLIGHT: Aircraft 2515 ran into aircraft 2895 which was parked on tarmac without lights.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: R.170 DATE: COMPOSITION: TCA/PCT/X FM MAA/XA RECOMMENDATIONS:))))
PRIMARY CAUSE: Negligence on part of pilot and ground crew. 9. ballinan	ACTION TAKEN: (2) DISCIPLINARY (B) TECHNICAL (C) OTHER))
secondary cause or contributing factors: A/C taxiied into A/C 2895 on tarmac.	Pilot & ground crew placed on charge. Pilot awarded 5 days C.B., 2 days penal forfeiture. Log Book endorsed. RECORDED BY DATE)
	CHECKED BY DATE))))))))))))))))