

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1						
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32						
CAUSES OF ACCIDENTS																			CAUSES																		
PILOT																			ENGINE FAILURE																		
OTHERS																			AIRFRAME FAILURE																		
UNIT																			MISCELLANEOUS																		
C.F.S.																			HAND O.																		
Trenton, Ont.																			INSTS.																		
# 1																			WEATHER																		
Main Aerodrome Trenton																			DRKNS.																		
COM.																			ALG SURF.																		
PLACE																			OTHER																		
DATE 9-2-42																			UND TO																		
TIME 1600																			PRIMARY																		
H.Q. FILE																			TAXIING																		
A/C TYPE																			LANDING																		
Harvard II																			FLIGHT																		
Harvard I																			STATRY																		
No. 3222																			FATAL																		
1342-D																			INJ.																		
CRASH CAT. D ₄																			3RD.																		
SE x ME																			S.																		
DAY x NIGHT																			N.																		
NAME																			RANK																		
NO.																			DUTY																		
INJURIES																			SERIOUS																		
Barrett, J.F.																			J3740																		
FI																			Uninjured																		
Degenais, J.P.																			R77235																		
P																			Uninjured																		
CARD SERIAL NO.																																					
TYPE A/F & ENGINE																			No.																		
EXTENT OF DAMAGE																			REPORT FORM																		
SERIAL No.																			DATE																		
HOURS FLOWN BY PILOTS																																					
INST.																			NIGHT																		
ON TYPE																			TOTAL																		
DUAL																			SOLO																		
DUAL																			SOLO																		
LAST 6 MOS																																					
Harvard																			3222																		
Slight																																					
Harvard																			1342																		
Slight																																					
Wasp																			4108																		
Nil																																					
Wasp																			4789																		
Nil																																					
SIGNAL No. & DATE																			UNIT No. & DATE																		
COM. No. & DATE																			REPORT																		
FILE																			DATE																		
A931																																					
NATURE OF ACCIDENT																																					

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER *RL70*

Stationary (3222)

OR COMMANDING OFFICER'S REPORT:

RL70

Taxiing on tarmac. (1342)

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

7/1/50 / PCT / XGI ✓

Harvard #1342 while taxiing on the tarmac slid into Harvard #3222. The port aileron and main plane of #1342 struck the starboard main plane of #3222. The fabric of #1342 aileron was ripped. Damage was extended to pitot head, starboard wing tip and main plane of #3222.

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE: *plane of #3222.* Nil

~~Congested taxi area and slippery condition of tarmac caused by heavy snowfall.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

9. collision

(9)

No blame attached to the pilot.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Aircraft skidded sideways overrunning the wing tip of another parked aircraft.~~

RECORDED BY

DATE

CHECKED BY

DATE