

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

Solo practice, spins aerobatics, precautionary landing & steep turn

RL70

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

FB/HOP/ES/PM/M/O ✓

After checking his cockpit the pilot took off & at 700 ft the engine spluttered & missed. Forced landing.

RECOMMENDATIONS:

PRIMARY CAUSE:

Nil

~~Engine failure due to icing resulting in loss of power.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

15. Forced Land

Nil

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

20. ~~Engine trouble - Accident~~
~~Forced landing damaging ring cowl, oil vent lines, starboard wheel well fairing.~~

RECORDED BY

DATE

CHECKED BY

DATE