

DUTY ON WHICH ENGAGED: COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: Formation flight. Court of Inquiry NATURE OF ACCIDENT AND STAGE OF FLIGHT: A/C caught in slipstream of leading COMPOSITION: A/C on take off and U/C struck runway and was damaged. Pilot attempt-Members - 7/0 D.Z.T. Wood No. 13 O.T.S. ed landing with undercarriage in F/O C. Scarr No. 122 (Composite) Sqn. intermediate position but it collapsed RECOMMENDATIONS 1. That an order be premalgated prohibiting formation and aircraft swung off runway. take-offs in multi-engined aircraft on this station. PRIMARY CAUSE: 2. That all pilots be instructed ust to retract Carelessness on part of pilot in the undercarriage until the aircraft is safely that he took off too close behind airborne. leader cousing starboard wheel to **ACTION TAKEN:** strike ground when caught in the (A) DISCIPLINARY (B) TECHNICAL (C) OTHER **H**11 slinetream of leader. Conclusions of A.I.B. celdent caused by carelessness of pilot in that he: (1) Book off too close to leader. (2) Rmised u ndercarriage too soon. SECONDARY CAUSE OR CONTRIBUTING FACTORS: (3) Attempted landing with undercarriage down. ittempted to bandivith starboard RECORDED BY DATE undercarriage partially locked causing aircraft to swing. R.C.A.F. FORM L20 REQ. 1247 10M-15-11-4 CHECKED BY