

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER
OR COMMANDING OFFICER'S REPORT:

Practicing forced landings.

RL70

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

Engine failed to start immediately when throttle opened rolled along ground until wheels struck soft spot in snow then aircraft turned over.

15FM/901/2001/104/14

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

~~Failure of engine to start immediately after gliding approach, due to not warming up engine.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil

16. Other

(16)

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Aircraft hit snow bank and turned over.~~

26. Engine trouble - Accident

(26)

RECORDED BY

DATE

CHECKED BY

DATE