

DUTY ON WHICH ENGAGED: Instrument flying.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: Investigating Officer Report
NATURE OF ACCIDENT AND STAGE OF FLIGHT: Instructor in front cockpit - brakes too harshly-on landing A/C nosed over.	DATE: 25-3-42 KM/ATTIPEM JUEP COMPOSITION:
)	RECOMMENDATIONS:
PRIMARY CAUSE: Carelessness, Pilot turned the	The question of this Officer's future employment or recategorization will be dealt with when he returns to duty.
a/c upside down possibly through	
a/c upside down possibly through	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
a/c upside down possibly through	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER P/O Sleep removed from Instructor duties pending disciplinary action.
a/c upside down possibly through	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER P/O Sleep removed from Instructor duties pending
a/c upside down possibly through	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER P/O Sleep removed from Instructor duties pending disciplinary action. Conclusions of A.I.B.
a/c upside down possibly through hersh use of brakes. That secondary cause or contributing factors:	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER P/O Sleep removed from Instructor duties pending disciplinary action. Conclusions of A.I.B.