

))	DUTY ON WHICH ENGAGED: Circuits and landings night flying.	COURT OF INQUIRY, INVESTIGATING OFFICER IN A PROPERTY OR COMMANDING OFFICER'S REPORT: R170
)	Pupil pilot carrying out solo circuits by night suffered engine failure, at a height of 700 feet.	DATE: COMPOSITION:
)	He forced landed 2 miles west of Collins Bay village doing considera damage to the a-c. PRIMARY CAUSE:	BECOMMENDATIONS: ble Nil
))))	17. Forced Landing	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER The pupil pilot is unable to give any information as to why it was necessary to force landing.
)	Crashed while carrying out a forced landing at night. The Engine Trackle	RECORDED BY DATE THECKED BY DATE THECKED BY DATE THECKED BY DATE