

DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER	) /
Practicing of precautionary landings		er's Ren
At 200 ft very bumpy conditions were experienced and the a/c appeared to go out of control, and after one flat turn struck	DATE: COMPOSITION:	
the ground in a horizontal positio	n.	
PRIMARY CAUSE: Error of judgment.		
(10) o. ralout	WACTION TAKEN:	
(19 out y least	(A) Disciplinary (B) Technical (C) Other  Fupil interviewed by Chief Instructor, Investored proceeding.	stigation
	rupli interviewed by Uniel Instructor, inves	tigation
SECONDARY CAUSE OR CONTRIBUTING FACTORS:  A/S stalled and hit ground.	rupli interviewed by Uniel Instructor, inves	etigation