

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

R.170

Machine on ski landing overran
snow surface & dropped 3' onto
paved runway, causing structural
failure of starboard oleo leg tube
support at weld.

COMPOSITION:

Lt/P-0

RECOMMENDATIONS:

PRIMARY CAUSE:

Aerodrome conditions

1. Overshot

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Structural failure of starboard oleo leg.~~

RECORDED BY

DATE

CHECKED BY

DATE