

## CASPIR Aircraft Accident Cards

---

**Serial:** AR935

**Title:** Airspeed Oxford Mk. I serial:AR935 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1942-April-15. Oxford s/n AR935. This accident involved 1 person. Archer DW

**Keywords:** RAFOxford ,AR935,34 SFTS,34 Service Flying Training School,Aerodrome,1942-April-15,ArcherRCAF L20

**Created:** 1942-04-15

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#AR935>



DUTY ON WHICH ENGAGED:

Local solo.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

R170

COMPOSITION:

Pilot made a normal approach landing but in so doing the port tyre burst, a/c swung off runway into soft ground where the wheels sank in and a/c overturned.

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

~~Tyre burst, A/C swung off runway and turned over in soft ground. while landing with drift.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

A/C overturned on soft ground.

37. Tire Burst.

RECORDED BY

DATE

CHECKED BY

DATE