

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1		
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32		
PILOT		OTHERS		AIRFRAME FAILURE										ENGINE FAILURE																			
CAUSES OF ACCIDENTS																																	
UNIT 124 Ferry SQDN COM. 3										PLACE Aerodrome Millinocket										DATE 17-4-42 TIME 1645				H.Q. FILE 1300-BM682									
A/C TYPE Oxford										No. BM682					CRASH CAT. C					SE X		ME X		DAY X		NIGHT							
NAME										RANK		No.		DUTY		INJURIES						SERIOUS											
Smith G.										P/O		656421		Pass.		Uninjured.						FATAL		INJURY									
Vollick										Cpl.				Crew.		"																	
																								CARD SERIAL NO.									
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS																					
Oxford		BM682										INST.		NIGHT		ON TYPE				TOTAL		LAST 6 MOS.											
																		DUAL SOLO		DUAL SOLO													
SIGNAL No. & DATE		UNIT No. & DATE				COM No. & DATE				REPORT				FILE				DATE															
A-326		18-4-42																															
NATURE OF ACCIDENT																																	

13
 18
 17
 16
 15
 14
 13
 12
 11
 10
 9
 8
 7
 6
 5
 4
 3
 2
 1
 13
 18
 17
 16
 15
 14
 13
 12
 11
 10
 9
 8
 7
 6
 5
 4
 3
 2
 1
 13
 18
 17
 16
 15
 14
 13
 12
 11
 10
 9
 8
 7
 6
 5
 4
 3
 2
 1

HAND Q.
 INSTS.
 WEATHER
 DRKNS.
 ALG SURF.
 OTHER
 UND/TD
 PRIMARY
 TAKING
 LANDING
 TAKE-OFF
 FLIGHT
 STAFFRY
 FATAL
 INJ.
 3rd. S.

MISCELLANEOUS CAUSES
 STAGE OF FLIGHT

DUTY ON WHICH ENGAGED:

Ferrying.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

15/11/55

COMPOSITION:

**A/C ground looped while landing
and wheel struck boulder off edge
of runway.**

RECOMMENDATIONS:

PRIMARY CAUSE:

2. Landing

(2)

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY

DATE

CHECKED BY

DATE