

CASPIR Aircraft Accident Cards

Serial: 3771

Title: North American Harvard Mk. II / 2 serial:3771 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1942-May-05. Harvard II s/n 3771. This accident involved 1 person. Rowe CL

Keywords: RCAFHarvard II,3771,8 SFTS,8 Service Flying Training School,Scoudouc Aerodrome,1942-May-05,RoweRCAF L20

Created: 1942-05-05

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#3771>

DUTY ON WHICH ENGAGED:

Practice sequence 13.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

R170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

A/C swerved on landing, pilot opened throttle, vicious ground loop resulted. *v/c collapsed*

DATE:

COMPOSITION:

23/10/57 ✓

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

~~Inexperience on the part of the pupil in that he allowed aircraft to swerve on landing.~~

SWUNG

(2)

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log Book endorsed: ground loop (inexperience.)

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Aircraft ground looped.~~

RECORDED BY

DATE

CHECKED BY

DATE