

CASPIR Aircraft Accident Cards

Serial: AJ936

Title: North American Harvard Mk. II / 2 serial:AJ936 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1942-May-13. Harvard s/n AJ936. This accident involved 1 person. Wright JH

Keywords: RAFHarvard ,AJ936,41 SFTS,41 Service Flying Training School,R1 Ralph,1942-May-13,WrightRCAF L20

Created: 1942-05-13

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ936>

DUTY ON WHICH ENGAGED:

Forced landing exercises.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

FR/ROD/ES/WH/G/E ✓

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Forced landing due to shortage of fuel to engine.

DATE:

COMPOSITION:

Joint of Petrol Pipe from engine became detached.

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Joint of petrol pipe from engine pump became detached.~~

FORCED LANDING

(7)

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Forced landing.~~

(25)

~~FIRE IN AIR~~

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____