

· · · · · · · · · · · · · · · · · · ·	
) DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT: R170
Night flying training.	
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	COMPOSITION: LM/ANT/ PEM/UBP
Aircraft swung on landing while	COMPOSITION: 2M/MIVI
pilot was carrying out night flying)
training. Brakes were applied 'too harshly and aircraft tipped up on nose damaging propellor.	RECOMMENDATIONS:
) PRIMARY CAUSE:	Nil
Inexperience on part of pilot.	
SWUNG	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) OTHER
2	Nil
) SECONDARY CAUSE OR CONTRIBUTING FACTORS:	
Aircraft tipped up on nose.	RECORDED BY DATE
}	CHECKED BY DATE