

	50000000000000000000000000000000000000))))))))))))))))))))
)	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFIC	ER	
)	Test flight.	OR COMMANDING OFFICER'S REPORT:		`
)			R.170	,
,	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:	Jespenjerje)
,	Forced landing after takeoff, as height could not be maintained	COMPOSITION:	1 - de Barlo)
)	on one engine.	·		Ť
)	on one engine.)
)		RECOMMENDATIONS:)
)				Ý.
,	PRIMARY CAUSE:			.,
<i>}</i>	Failure of one engine.)
)	15. FORCED LAND.)
)	TO. TONCES LIMITO.)
)	115	ACTION TAKEN: (A) DISCIPLINARY (B) TECHNICAL (C) C	THER)
)	(13)	All pumps ordered to be)
)		& care taken that the fl	low of fuel is normal.	-
,		prior to flight. Pilots	made thoroughly	
,	•	conversant with the tank	c & line installations) mailtean
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS: &	warned of possibilities	3 & precaution of using	
}	A/C made force landing.	interconnecting cocks.	RECORDED BY DATE	
ì	/7/			
)	(20)		CHECKED BY DATE	ikan.
,	R.C.A.F. FORM L20 REQ. 1247 19M-15-11-41		CHECKED BY DATE	<i>)</i>
)