

CASPIR Aircraft Accident Cards

Serial: AS213

Title: Airspeed Oxford Mk. II serial:AS213 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1942-May-21. Oxford s/n AS213. This accident involved 1 person. Buchanan WS

Keywords: RAFOxford ,AS213,35 SFTS,35 Service Flying Training School,R1 Hamlin,1942-May-21,BuchananRCAF L20

Created: 1942-05-21

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#AS213>

DUTY ON WHICH ENGAGED:

Practice single engine flying,
steep turns and single engine
landing.

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

A/C swung after heavy single
engine landing, STBD U/C collapsed.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

R.170

DATE:

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Error of judgment, on the part of
the pilot in that he misjudged his
height on landing after faulty
execution of a single engine
approach.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Further instruction to be given.

SWUNG

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Aircraft half ground looped with
extensive damage to it:~~

UIC STRAIN

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____