

CASPIR Aircraft Accident Cards

Serial: AS607

Title: Airspeed Oxford Mk. I serial:AS607 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 2 aircraft on 1942-May-31. They are: Oxford s/n AS181, Oxford s/n AS607. This accident involved 2 people. Atkinson B, Hayes F

Keywords: RAFOxford ,AS607,35 SFTS,35 Service Flying Training School,Aerodrome,1942-May-31,Atkinson,HayesRCAF L20

Created: 1942-05-31

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#AS607>

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

MOLT

Training.

OR COMMANDING OFFICER'S REPORT:

R.170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

P/O Atkinson in AS607 taxied into AS181 which was stationary on tarmac.

COMPOSITION:

For brake failed to respond when moving to STB. developed.

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Brake failure.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

~~Error of judgement on part of pilot in that he failed to switch off when he realised the brake was ineffective.~~

Further instruction given. Admonished by Station Commander. Log Book endorsed "Error of Judgment Taxiing".

COLLISIONS

9

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Stbd. wing-tip of AS607 struck the nose of AS181.~~

36

BRAKE FAILURE

RECORDED BY

DATE

CHECKED BY

DATE