

## CASPIR Aircraft Accident Cards

---

**Serial:** AJ924

**Title:** North American Harvard Mk. II serial:AJ924 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 1 aircraft on 1942-June-01. Harvard II s/n AJ924. This accident involved 2 people. Perry HM, Rowland WB

**Keywords:** RAFHarvard II,AJ924,41 SFTS,41 Service Flying Training School,Weyburn Aerodrome,1942-June-01,Perry,RowlandRCAF L20

**Created:** 1942-06-01

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ924>



DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER  
OR COMMANDING OFFICER'S REPORT:

R170

**Forced landings and steep turns.**

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

LU/PSU ✓

**Aircraft undershot and undercarriage**

COMPOSITION:

**struck mound of earth outside perimeter  
track.**

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

**Undershooting.**

**UNDERSHOT**

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed, "Error of judgment!"

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Aircraft struck mound of earth.~~

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_