

CASPIR Aircraft Accident Cards

Serial: FE278

Title: North American Harvard Mk. IIB serial:FE278 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1942-June-14. Harvard II s/n FE278. This accident involved 2 people. Mackenzie CG, Walker J

Keywords: RAFHarvard II,FE278,41 SFTS,41 Service Flying Training School,Aerodrome,1942-June-14,Mackenzie,WalkerRCAF L20

Created: 1942-06-14

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE278>

DUTY ON WHICH ENGAGED:

Circuits and landings.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

R170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Crosswind landing, A/C swung after landing. Starboard undercarriage collapsed, in soft ground.

DATE:

COMPOSITION:

LS/PSS/I/USG/wwc ✓

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

~~Crosswind landing, aircraft swung after landing.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Starboard undercarriage collapsed.~~

34. J.C. STRAIN

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____