



DUTY ON WHICH ENGAGED:

Flying training.

COURT OF INQUIRY, INVESTIGATING OFFICER  
OR COMMANDING OFFICER'S REPORT:

11/11/57 R170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

F/O White failed to observe stationary aircraft parked on tarmac and taxied Harvard 3791 into Harvard 2604.

DATE:  
COMPOSITION:

TCA/PCT ✓  
MA/XA

RECOMMENDATIONS:

N11

PRIMARY CAUSE:

~~Gross carelessness on part of F/O G.E. White, in failing to observe stationary aircraft.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Disciplinary action taken against F/O White. Pilot personally admonished and Log Book endorsed for "Gross Carelessness" by Commanding Officer.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Harvard 3791 taxied into Harvard 2604.~~

RECORDED BY \_\_\_\_\_ DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_ DATE \_\_\_\_\_