

· · · · · · · · · · · · · · · · · · ·	
DUTY ON WHICH ENGAGED:	
Practice solo flight.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:
NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE: 29-6-42 INVESTIGATING OFFICERS REPORT
Aircraft crashed into Lake Memphred Vermont, Aircraft flew up and down	nagon Position: 14CG/POL/PSU
take twice, and on the second appro-	Soch S/L P.E. David (C1020) No. 33 E E E E
a/c actually touched the water. As	rcraft Cap de la Madeleine.
struck the water and sank in about 40 feet of water.	RECOMMENDATIONS:
	(a) That the relevant facts of this case be pub-
PRIMARY CAUSE:	TICINOU AU UMIUS.
The pupil pilet was carrying out	(b) That Commanding Officers and Chief Sungaria
unauthorized low flying over Lake	The more severe in dealing with
Memphremagog, and due to glassy	Breaches of Flying Regulations.
water misjudged his height and	ACTION TAKEN:
crashed	(A) DISCIPLINARY (B) TECHNICAL (C) OTHER
20. FLEN INTO (20)	Nil.
20. FLEW INTO DESUNDE	Conclusions of A.I.B:
, 43	Pupil pilot, while deliberately carrying out
SECONDARY CAUSE OR CONTRIBUTING FACTORS:	unauthorized low flying, crashed into a lake when
Aircraft crahsed into the water	he misjudged his height due to the glassy surface of the water.
and sank.	RECORDED BY DATE
45 D. 1 12 Mills	DATE
42. UNAVTH LOW. FLYING (AL) R.C.A.F. FORM LZO REG. 1247 10M-15-11-41	