

CASPIR Aircraft Accident Cards

Serial: 8265

Title: Avro Anson Mk. II serial:8265 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1942-June-10. Anson II s/n 8265. This accident involved 2 people. Peacock FH, Thomas J

Keywords: RCAFAnson II,8265,16 SFTS,16 Service Flying Training School,R1 Cayuga,1942-June-10,Peacock,ThomasRCAF L20

Created: 1942-06-10

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#8265>

DUTY ON WHICH ENGAGED:

Night flying instruction.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

R170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

A/C swerved to the right on landing, instructor opened STED throttle but could not correct swing. No brakes on instructors side, A/C struck control hut.

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

~~Flat tyre.~~

(2)

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil

SWUNG.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~A/C struck control hut due to violent swing which instructor was unable to correct.~~

(31)

RECORDED BY

DATE

CHECKED BY

DATE