

## CASPIR Aircraft Accident Cards

---

**Serial:** 6092

**Title:** Avro Anson Mk. I serial:6092 Accident Card

**Author:** Royal Air Force (RAF)

**Subject:** This accident involved 2 aircraft on 1942-June-22. They are: Anson I s/n 6127, Anson I s/n 6092. This accident involved 4 people. Earp RL, Harbot PR, Martin SW, Walker J

**Keywords:** RAFAnson I,6092,41 SFTS,41 Service Flying Training School,Aerodrome,1942-June-22,Earp,Harbot,Martin,WalkerRCAF L20

**Created:** 1942-06-22

**Link:** <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#6092>

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1	19					
JUL	TECH.	DISOB.	NEG NCE	INEXP NCE	MISCEL.	INSTRUCT.	FLT CONTR.	OTHERS	PRIMARY	FL CONTR.	MOV SURFS.	STAB SURFS.	W STRUTS	LAND GEAR	FLOATS	FUSE OR HULL	TAIL SKID OR W.	ENGINE MOUNT	MISCEL.	UND TD	PRIMARY	FUEL SYS.	COOL SYS.	IGNIT SYS.	LUB'N SYS.	ENG STR.	AIRSCREW A.	ENG CONTR.	MISCEL.	UND TD	PRIMARY	18					
2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33						
PILOT		OTHERS		AIRFRAME FAILURE										ENGINE FAILURE																							
CAUSES OF ACCIDENTS																																					
UNIT <b>41 S.F.T.S.</b>		COM. # <b>2</b>		PLACE <b>Main Aerodrome Weyburn</b>										DATE <b>22-6-42</b>		TIME <b>2250</b>																					
A/C TYPE <b>Anson I</b>		No. <b>6127</b>		CRASH CAT. <b>C16</b>		SE <b>ME</b>		DAY <b>x</b>		NIGHT <b>x</b>																											
A/C TYPE <b>Anson I</b>		No. <b>6092-D</b>		CRASH CAT. <b>C7</b>		SE <b>x</b>		DAY <b>x</b>		NIGHT <b>x</b>																											
NAME										RANK		No.		DUTY		INJURIES				SERIOUS																	
Walker, J.										LAC		1344927		PP		6092		Uninjured				FATAL INJURY															
Martin, S.W.										F/O		42623		PP		6092		Uninjured				FATAL INJURY															
Harbot, P.R.										LAC		1239305		FI		6092		Uninjured				FATAL INJURY															
Earp, R.I.										W/O		562341		FI		6092		Uninjured				FATAL INJURY															
																						CARD SERIAL No.															
TYPE A/F & ENGINE		No.		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		HOURS FLOWN BY PILOTS																									
Anson I		6127		Serious								INST. NIGHT		ON TYPE		TOTAL		LAST 6 MOS.																			
Cheetahs AF30416/S10256		Slight								SW		22 25		25 60		70 84																					
Anson I		6092		Serious						SW		22 73		25 80		80 140																					
Cheetahs AF30524/P10163		Slight																																			
SIGNAL No. & DATE				UNIT No. & DATE				COM. No. & DATE				REPORT				FILE				DATE																	
A-64 23-6-42																																					
A-65																																					
NATURE OF ACCIDENT																																					
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33					
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32	33					

MISCELLANEOUS CAUSES

STAGE OF FLIGHT

HAND O.  
 INSTS.  
 WEATHER  
 DRKNS.  
 ALG SURF.  
 OTHER  
 UND TD  
 PRIMARY  
 TAXIING  
 LANDING  
 TAKE-OFF  
 FLIGHT  
 STATRY  
 FATAL  
 INJ.  
 INJURY  
 3RD.

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

night

Night flying practice and instruction.

OR COMMANDING OFFICER'S REPORT:

R170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Aircraft taxied into A/C 6127 proceeding on to the taxiing strip.

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

Nil

~~Pilot of ANSON 6092 failed to see navigation lights on Anson 6127.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed "Carelessness". "During night flying practice failed to notice an aircraft immediately in front of him and taxied into it."

9

9. COLLISIONS.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Anson 6092 taxied into Anson 6127.~~

RECORDED BY

DATE

CHECKED BY

DATE