

CASPIR Aircraft Accident Cards

Serial: 8257

Title: Avro Anson Mk. II serial:8257 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1942-June-24. Anson II s/n 8257. This accident involved 2 people. Henderson FR, Laird DC

Keywords: RCAFAnson II,8257,5 SFTS,5 Service Flying Training School,Aerodrome,1942-June-24,Henderson,LairdRCAF L20

Created: 1942-06-24

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000123#8257>

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Practising precautionary landings.

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

While practising precautionary landings starboard engine failed at approximately 20 feet. Unable to maintain height aircraft crashed into wood.

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Starboard engine failure.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

17

17. FORCED LANDING

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~A/C stalled and mushed down through the trees.~~

26. ENGINE TROUBLE-

26

ACCIDENT.

RECORDED BY

DATE

CHECKED BY

DATE