

CASPIR ARCHIVAL METADATA

Serial:	5841
Title:	de Havilland Moth, Tiger I serial:5841 Accident Card
Author:	Royal Canadian Air Force (RCAF)
Subject:	This accident involved 1 aircraft on 1942-June-01. Tiger Moth s/n 5841. This accident involved 2 people. Miller HE, Riley HE
Keywords:	RCAFTiger Moth ,5841,2 FIS,2 Flying Instructor School,Aerodrome,1942-June-01,Miller,RileyRCAF L20
Created:	1942-06-01
Link:	https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001626#5841

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

R170

Mutual instruction.

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

A/C ground looped after landing.

COMPOSITION:

23/100

Pupil failed to prevent swing to right, right wheel hit contact light throwing aircraft over on to its left wing, causing the ground loop.

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

~~Error in judgment of pilot, in that he failed to apply corrective action soon enough to prevent ground loop in landing.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed.

2

2. SWUNG

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Aircraft swung to right struck contact light, went up on left wing and ground looped.~~

RECORDED BY

DATE

CHECKED BY

DATE