

CASPIR Aircraft Accident Cards

Serial: AS698

Title: Airspeed Oxford Mk. I serial:AS698 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1942-June-05. Oxford s/n AS698. This accident involved 1 person. Warburton A

Keywords: RAFOxford ,AS698,35 SFTS,35 Service Flying Training School,R1 Hamlin,1942-June-05,WarburtonRCAF L20

Created: 1942-06-05

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#AS698>

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Solo training flight.

OR COMMANDING OFFICER'S REPORT:

R170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

Pupil landed heavily after making glide approach, and tail oleo was driven into the fuselage.

COMPOSITION:

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

~~Error of judgment, of an inexperienced pilot.~~

4. Heavy

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Extra instruction in glide approaches.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~tail oleo was driven into the fuselage during a heavy landing.~~

34. *W/C* STRAIN

R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____