

CASPIR Aircraft Accident Cards

Serial: AS706

Title: Airspeed Oxford Mk. II serial:AS706 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1942-June-29. Oxford s/n AS706. This accident involved 2 people. Bundy FW, Carter MLH

Keywords: RAFOxford ,AS706,35 SFTS,35 Service Flying Training School,Aerodrome,1942-June-29,Bundy,CarterRCAF L20

Created: 1942-06-29

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200001215#AS706>

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY. INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

Dual instructions in taking off and landing.

R170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

After running a short distance, the port tyre burst and the a/c swung left and tipped up on to its nose.

COMPOSITION:

4.3.78

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

~~Failure of the inner tube of the port landing wheel.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil

2. SWUNG.

(2)

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~A/C swung and tipped up on its nose.~~

37. TIRE BURST.

(37)

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____