

CASPIR Aircraft Accident Cards

Serial: 3614

Title: Fleet Fort serial:3614 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1942-June-25. Fleet Fort II s/n 3614. This accident involved 2 people. Doherty JN, Herd JWH

Keywords: RCAF Fleet Fort II,3614,3 WS,3 Wireless School,Stevenson Field
Winnipeg,1942-June-25,Doherty,Herd RCAF L20

Created: 1942-06-25

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000741#3614>

DUTY ON WHICH ENGAGED:

Wireless training exercise.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

R170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

COMPOSITION:

Pilot made severe application of right brake, A/C ground looped, tail of A/C lifted causing propeller to strike ground.

7M/7.00/18

RECOMMENDATIONS:

Nil

~~Trans-Canada Airlines a/c taxied in front of our a/c forcing pilot to use this method to avoid ramming into the T.C.A. passenger ship.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

2. SWUNG

2

Nil

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Aircraft ground looped on severe use of right brake, tail lifted causing the propeller to strike ground.~~

RECORDED BY

DATE

CHECKED BY

DATE