

)	DUTY ON WHICH ENGAGED: Training flight.	COURT OF INQUIRY, INVESTIGATING OFFICER OR COMMANDING OFFICER'S REPORT:)
))	NATURE OF ACCIDENT AND STAGE OF FLIGHT: When landing during check of pupil	DATE)
)	ability to execute precautionary landings in daytime, pupil without warning closed throttle and pulled)
)	back control column when about 10' up, causing aircraft to stall and flick, the right wing striking the	RECOMMENDATIONS:)
)	Primary cause: ground. Pupil closed throttle too early.	Nil	`
)	Garelessness on part of pupil. 4. Hrany.	ACTION TAKEN:)
)	(4)	(A) Disciplinary (B) Technical (C) Other Instructor's log book endorsed "Carelessness")
)	CECONDADY CAUGE OF CONTRACTOR)
)	SECONDARY CAUSE OR CONTRIBUTING FACTORS: Wing tip hit ground.	RECORDED BY DATE)
)	R.C.A.F. FORM L20 REQ. 1247 10M-15-11-41	CHECKED BY DATE	_
)) 2