

CASPIR Aircraft Accident Cards

Serial: AJ938

Title: North American Harvard Mk. II / 2 serial:AJ938 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1942-July-19. Harvard s/n AJ938. This accident involved 1 person. Hayes RE

Keywords: RAFHarvard ,AJ938,41 SFTS,41 Service Flying Training School,Aerodrome,1942-July-19,HayesRCAF L20

Created: 1942-07-19

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ938>

DUTY ON WHICH ENGAGED:

COURT OF INQUIRY, INVESTIGATING OFFICER

Powered approach.

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

DATE:

R.170

A/C swung and ground looped.

COMPOSITION:

2/1/50/wwc ✓

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Cross wind caused A/C to swing to right on landing.~~

~~Failure to apply right rudder.~~

2. Sweung

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

NIL.

2

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

A/C ground looped.

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____