

CASPIR Aircraft Accident Cards

Serial: FE301

Title: North American Harvard Mk. IIB serial:FE301 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1942-July-30. Harvard II s/n FE301. This accident involved 2 people. Hamilton RS, Lambeth D

Keywords: RAFHarvard II,FE301,41 SFTS,41 Service Flying Training School,Aerodrome,1942-July-30,Hamilton,LambethRCAF L20

Created: 1942-07-30

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#FE301>

DUTY ON WHICH ENGAGED:

Testing aircraft for Night Flying.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

A/C swung on landing.

DATE:

R.170

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Inability of pilot to correct swing.~~

Z. Seung (2)

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Nil.

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~A/C swung on landing.~~

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____