



DUTY ON WHICH ENGAGED:

Single engine landing on aerodrome.

COURT OF INQUIRY, INVESTIGATING OFFICER

R170

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Pupil landed and A/C ground looped to left.

DATE:

COMPOSITION:

*1/10/1971*

RECOMMENDATIONS:

Nil

PRIMARY CAUSE:

~~Crosswind and inexperience on part of pilot.~~

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

Log book endorsed "Inexperience."

*Z. Seung* (2)

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

Aircraft ground looped on landings.

RECORDED BY

DATE

CHECKED BY

DATE