



DUTY ON WHICH ENGAGED:

**Flying out A/C after forced landing.**

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

**A/C struck fence on take-off from field in which forced landing had been made.**

DATE:

**R170**

COMPOSITION:

*170/170*

RECOMMENDATIONS:

PRIMARY CAUSE:

~~Insufficient take-off surface.~~

*13. collisions*

*(13)*

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

**Nil**

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~Port engine apparently did not give full power on take-off.~~

~~A/C struck fence post with port propeller and force landed.~~

RECORDED BY \_\_\_\_\_

DATE \_\_\_\_\_

CHECKED BY \_\_\_\_\_

DATE \_\_\_\_\_