

32	31	30	29	28	27	26	25	24	23	22	21	20	19	18	17	16	15	14	13	12	11	10	9	8	7	6	5	4	3	2	1						
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24	25	26	27	28	29	30	31	32						
PILOT																	AIRFRAME FAILURE											ENGINE FAILURE									
OTHERS																	CAUSES OF ACCIDENTS											MISCELLANEOUS									
UNIT		COM.		PLACE		DATE		TIME		H.O. FILE		A/C TYPE		No.		CRASH CAT.		SE		ME		DAY		NIGHT		NAME		RANK		No.		DUTY		INJURIES		SERIOUS	
32 R.F.W.F.		4		M.A.		9-7-42		1215		1700-FJ901		Steerman		FJ901		C 2		x				x				Wilder L.		LAC.		1321872		Uninjured.		FATAL INJURY			
TYPE OF A/C		TYPE OF ENGINE		TYPE A/F & ENGINE		EXTENT OF DAMAGE		REPORT FORM		SERIAL No.		DATE		INST.		NIGHT		ON TYPE		TOTAL		LAST 6 MOS.		CARD SERIAL No.		NAME		RANK		No.		DUTY		INJURIES		SERIOUS	
STEERMAN		STEERMAN		FJ901										3				27		35																	
CATEGORY		SIGNAL No. & DATE		UNIT No. & DATE		COM. No. & DATE		REPORT		FILE		DATE		STAGE OF FLIGHT		TAXIING		LANDING		TAKE-OFF		FLIGHT		STATRY		FATAL		INJ.		3RD		5TH					
A 213		9-7-42												FLIGHT																							
NATURE OF ACCIDENT																																					

DUTY ON WHICH ENGAGED:

Solo practice.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

Ground looped on landing.

DATE:

LS/PB

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

Inexperienced pilot.

L. Suung (2)

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY

DATE

CHECKED BY

DATE