

CASPIR Aircraft Accident Cards

Serial: 3614

Title: Fleet Fort serial:3614 Accident Card

Author: Royal Canadian Air Force (RCAF)

Subject: This accident involved 1 aircraft on 1942-July-28. Fleet Fort II s/n 3614. This accident involved 2 people. Dronfield RS, Labella AJ

Keywords: RCAFFleet Fort II,3614,3 WS,3 Wireless School,Stevenson Field
Winnipeg,1942-July-28,Dronfield,LabellaRCAF L20

Created: 1942-07-28

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000741#3614>

DUTY ON WHICH ENGAGED:

Wireless training exercises.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

A/C caught on fire when taxiing
after landing.

DATE:

7/19/66 ^{PM} 10/17/66

COMPOSITION:

RECOMMENDATIONS:

PRIMARY CAUSE:

Break in fuel inlet elbow to
carburettor.

ACTION TAKEN:

(A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

RECORDED BY _____

DATE _____

CHECKED BY _____

DATE _____