

CASPIR Aircraft Accident Cards

Serial: AJ938

Title: North American Harvard Mk. II / 2 serial:AJ938 Accident Card

Author: Royal Air Force (RAF)

Subject: This accident involved 1 aircraft on 1942-August-04. Harvard II s/n AJ938. This accident involved 2 people. Easterman LD, Pirnie F

Keywords: RAFHarvard II,AJ938,41 SFTS,41 Service Flying Training School,Aerodrome,1942-August-04,Easterman,PirnieRCAF L20

Created: 1942-08-04

Link: <https://caspir.warplane.com/aircraft/serial-search/aircraft-no/200000852#AJ938>

DUTY ON WHICH ENGAGED:

A/C test.

COURT OF INQUIRY, INVESTIGATING OFFICER

OR COMMANDING OFFICER'S REPORT:

R.170

NATURE OF ACCIDENT AND STAGE OF FLIGHT:

A/C swung on landing.

DATE:

COMPOSITION:

LS/PSS/UTWF/USS ✓

1/2 damaged



RECOMMENDATIONS:

NIL.

PRIMARY CAUSE:

Shearing of location pin on tail wheel.

2. Swing (2)

ACTION TAKEN:

NIL. (A) DISCIPLINARY (B) TECHNICAL (C) OTHER

SECONDARY CAUSE OR CONTRIBUTING FACTORS:

~~A/C swung on landing.~~

32. 1/2 defect.

(35)

RECORDED BY _____ DATE _____

CHECKED BY _____ DATE _____