

)	· , , , , , , , , , , , , , , , , , , ,		)))))))))	)
(	DUTY ON WHICH ENGAGED:	COURT OF INQUIRY, INVESTIGATING OFFIC	ER	)
)	TAXIING A/C TO MAINTENANCE HANGAR	OR COMMANDING OFFICER'S REPORT:	D 760	)
)	NATURE OF ACCIDENT AND STAGE OF FLIGHT:	DATE:	R.170	)
)	WHILE TAXIING PILOT ENDEAVOURED TO TURN	COMPOSITION: TOO!	R.170 PCT	)
)	CATHOUT MERMAN ON WING TIP AND STRUCK HANGAR			)
)		RECOMMENDATIONS:		)
)		Nil.		)
)		MIT		-
)	PRIMARY CAUSE:			
<b>'</b> )	GROSS CARELESSNESS			)
)	GROSS CARELESSNESS  G. Coellister			)
)	G	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  Pilot interviewed by Chief Instructor. Awarded 3 days  C.C. and his Log Book endorsed "Gross Carelessness."		
,	SECONDARY CAUSE OR CONTRIBUTING FACTORS:			}
, ,	Wing hit hangar doer.		RECORDED BY DATE	)
)	R.C.A.F. FORM LCO REG. 1247 10M-15-11-41		CHECKED BY DATE	)
			<b>)</b> ) ) ) ) ) ) ) .	)_