

Practice landing.	COURT OF INQUIRY, INVESTIGATING OFFICER  OR COMMANDING OFFICER'S REPORT:  R.170
NATURE OF ACCIDENT AND STAGE OF FLIGHT:  A/C ground looped on landing.	DATE:  COMPOSITION:  LS/PSS/wwc
Come de de la compansión de la compansió	RECOMMENDATIONS:  NiL.
PRIMARY CAUSE: Themperience.  2. Surung	ACTION TAKEN:  (A) DISCIPLINARY (B) TECHNICAL (C) OTHER  Pilot interviewed by Chief Instructor. Log Book endorsed "Inexperience."
secondary cause or contributing factors:  A/C ground looped,	RECORDED BY DATE
7 R.Q.A.F. FORM L29 REQ. 1217 16M—15-11-41	CHECKED BY DATE )